

# Gripstar Tex

## DATASHEET

Classification	Norm	Tarkett Value
Product type	EN ISO 26986	Expanded (cushioned) poly(vinyl chloride) floor covering
Domestic classification	ISO 10874	22 / 22+ Domestic general medium / Domestic general
Binder content	ISO 11638	Type I
Technical characteristics	Norm	Tarkett Value
Total thickness	ISO 24346	2.6 mm
Wear layer thickness	ISO 24340	0.20 mm
Total weight	ISO 23997	1530 g/m <sup>2</sup>
Performance for CE Marking	Norm	Tarkett Value
Declaration of Performance #	EN 14041	0007-0085-DOP-2024-10
Reaction to fire	EN 13501-1	Cfl-s1
Slip resistance	EN 13893	Class DS ( $\mu \geq 0.30$ )
Slip resistance (ramp test)	EN 16165 national Annex NB.2	R10
Electrostatic propensity	EN 1815	Antistatic ( $\leq 2$ kV)
Thermal resistance	ISO 10456	0.04 m <sup>2</sup> · K/W
Technical performance	Norm	Tarkett Value
Residual indentation	ISO 24343-1	$\leq 0.35$ mm
Impact sound reduction – $\Delta L_w$	EN ISO 717-2	18 dB
Colour fastness to light	ISO 105-B02	$\geq 6$
Chemical resistance	ISO 26987	Not affected
Underfloor heating		Suitable (subfloor maximum temperature 27°C)
Dimensional stability	ISO 23999	$\leq 0.15$ %
Curl resistance	ISO 23999	$\leq 8$ mm
Sustainability performance	Norm	Tarkett Value
Recyclability through ReStart®		Offcuts & post-use* – contact Tarkett for more information
Recycled content		32 %
TVOC emissions after 28 days	EN 16516	Gold ( $\leq 100$ µg/m <sup>3</sup> )
French VOC rating		A+
Phthalate content		Phthalate-free
Formaldehyde emission	EN 717-1	E1
Dimensions and designs		Tarkett Value
Roll		Roll 2 × 25 m Roll 3 × 25 m Roll 4 × 25 m
Number of designs available		31
Product ID		Tarkett Value
Domestic warranty (in years)		15

\* Loose-laid installed



The above information is subject to modification for the benefit of further improvement (20/03/2025). According to the European Regulation N°305/2011 for CE Marking, the Declarations of Performance are available on our website <https://www.tarkett.com>. Tarkett's instructions regarding installation, cleaning and maintenance should be observed. Please contact Tarkett at the address shown for the instructions.